


EXHIBIT 14



Unoccupied

Updated:

July 12, 2010

Drop	Date	BEDROOM #1				BEDROOM #2				LIVING ROOM				KITCHEN				BATHROOM			Pre test	Test	Result	Touch up units	Last Walk	Comments	Drop	
		Interior	Exterior	New Sash	Re-inspect date	Bottom sash Repair	Window contacts	Interior	Exterior	New Sash	Re-inspect date	Bottom sashes Repair	Interior	Exterior	New Sash	Re-inspect date	Bottom sashes Repair	Interior	Exterior	New Sash	Pre test	Test	Result	Touch up units	Last Walk	Comments		
101	6/11/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	no W6		N/A	N/A	N/A						Unoccupied. No W6 window sash unit not corr.	101	
201	5/5/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	no W6		N/A	N/A	N/A						No W6 window sash unit not complete	201	
301	5/4/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied. Will need to remove stops on all windows and re-caulk all six corners with Acryl-R	301
401	5/3/2010	yes	yes			5/20/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	401
501	5/4/2010	yes	yes						N/A	N/A	N/A			yes	yes			N/A	N/A								Occupied	501
102	5/7/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Occupied	102
202	5/5/2010	yes	yes	yes	6/10/2010	7/12/2010	yes	N/A	N/A	N/A	N/A		yes	yes	yes	7/12/2010	7/12/2010	N/A	N/A	N/A	N/A						Unoccupied. COMPLETED	202
302	5/4/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	302
402	5/3/2010	yes	yes			5/20/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	402
502	5/4/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Occupied	502
103	4/20/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Occupied	103
203	6/11/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Occupied	203
303	5/4/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Occupied	303
403	5/4/2010	yes	yes			5/20/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	403
503	5/4/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Unoccupied	503
104	6/10/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Occupied	104
204	5/17/2010	yes	yes	yes				yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Unoccupied	204
304	6/7/2010	yes	yes			5/27/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Occupied	304
404	6/7/2010	yes	yes			6/7/2010			N/A	N/A	N/A			yes	yes			N/A	N/A	N/A							Occupied	404
504	6/8/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A	N/A								Occupied	504
105	6/10/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Unoccupied	105
205	6/10/2010	yes	yes	yes	6/11/2010	7/12/2010	yes	N/A	N/A	N/A	N/A		yes	yes	yes	7/12/2010	7/12/2010	N/A	N/A	N/A	N/A						Unoccupied	205
305	4/20/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	305
405	5/11/2010	yes	yes			5/19/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Occupied	405
505	5/11/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Occupied	505
106	6/10/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	yes	6/10/2010	N/A	N/A	N/A	6/10/2010	N/A	N/A				Unoccupied model unit	106
206	5/10/2010	yes	yes	yes				yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Unoccupied	206
306	5/10/2010	yes	yes	yes	5/25/2010			yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A								Unoccupied	306
406	5/10/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Unoccupied	406
506	4/20/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Unoccupied	506
207	5/10/2010	yes	yes	yes	6/10/2010			yes	N/A	N/A	N/A			yes	yes	yes		N/A	N/A	N/A							Unoccupied	207
307	5/10/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied One new sash was installed in this unit	307
407	5/10/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Unoccupied	407
507	5/10/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Occupied	507
208	6/14/2010	yes	yes	yes	6/14/2010	7/12/2010	yes	N/A	N/A	N/A	N/A		yes	yes	yes	7/12/2010	7/12/2010	N/A	N/A	N/A	N/A						Unoccupied. Will need to remove stops on all windows and re-caulk all six corners with Acryl-R	208
308	5/10/2010	yes	yes			5/25/2010			N/A	N/A	N/A			yes	yes			N/A	N/A								Unoccupied	308
408	5/10/2010	yes	yes					N/A	N/A	N/A			yes	yes			N/A	N/A									Unoccupied	408
508	5/10/2010	yes	yes					N/A	N/A	N/A			yes	yes														

